

Subaru Phase 2 Front & Rear Stator Bushings 98 Up Impreza, Forester, Outback, Legacy and Baja Models



Front and Rear Stator Bushing with Installation Tool

Subaru 1998 and up equipped with the Phase II four speed transmission may show a code P0741 converter slip. The cause may be worn stator bushings allowing a loss in the converter apply circuit.

Front Stator Bushing #70428 Rear Stator Bushing #70429 Installation Tool #70331

Bushings are available separately

Your feedback is welcome on all our products!

Omega Machine & Tool, Inc.

"Precision and Innovation for Today"

* New Address *

2949 Promenade St # 100 West Sacramento CA 95691

Tel. 800 601 7722 – Fax 916 372 6020 www.omegamachine.com