

AW 55-50SN Case Repair
AW 55-51SN


**Before doing anything else be sure to
check the case for wear!**



The AW 55-50SN family of transmissions comes in Maximas, Saturn Vues, Volvos, and Saabs. Transmission failure is a result of spun and worn bushings. The case wears and the transmission loses its centerline, causing bushings to fail.

The top picture on the left shows the case wear, where the transfer gear sits in the case. Note the shiny wear mark in the bore.

The lower picture is of a case that has been sleeved to restore the stock fit.



One day service is available.

Your feedback is welcome on all our products!

Omega Machine & Tool, Inc.
"Precision and Innovation for Today"

*** New Address ***

2949 Promenade St # 100 West Sacramento
CA 95691

Tel. 800 601 7722 – Fax 916 372 6020
www.omegamachine.com

October 10, 2008