



No need to buy an expensive replacement new drum. Omega Machine & Tool, Inc. can now repair your ring cut drums. As an upgrade the drum comes with a new bronze bushing that is substantially wider. Bushing is available separately. Part #33438

Your feedback is welcome on all our products!

Omega Machine & Tool, Inc.

"Precision and Innovation for Today"

*** New Address ***

2949 Promenade St # 100
West Sacramento CA 95691
Tel. 800 601 7722 – Fax 916 372 6020
www.omegamachine.com